

Log of Daily Temperature & Humidity Checks in the Sterile Core*

Location	Acceptable Temp Ranges	Acceptable Humidity Ranges
Procedure Room	68° - 73°	30% - 60%
		30% - 60%
Medication Refrigerator **	36° - 46°	n/a

**If the temperature or humidity is outside accepted ranges, take immediate corrective action and document the results on the reverse side of this log form.*

Date/ Initial	Record	Procedure Room	Sterile Supply	When any value to the left is outside the acceptable range, you document what you did to resolve the issue in the column spaces below.	Medication Refrigerator
02/15/2023	Time	0840	0842	Temperature and Humidity of the sterile supply was noted to be outside the acceptable range, therefore we ensured the HVAC system was working properly, then we noted that the film on the windows was malfunctioned providing much of the afternoon sun rise in the temp and humidity in the sterile supply space. The compromised film was replaced 02/18/2023 T. Lair	0852
	Temp	70	76		38 degrees F
	Humidity				n/a
	Time				
	Temp				
	Humidity				n/a
	Time				
	Temp				
	Humidity				n/a
	Time				
	Temp				
	Humidity				n/a
	Time				
	Temp				
	Humidity				n/a
	Time				
	Temp				
	Humidity				n/a
	Time				
	Temp				
	Humidity				n/a
	Time				
	Temp				
	Humidity				n/a

****Remember that the refrigerator must be plugged directly into your emergency power supply outlet in order to safeguard against interrupted power supply from the weekends when the center is closed. Otherwise, the penny on icecube technique will need to be implemented.**